

Federal 6-25

Inspection# 673401912

Rills on access road and
leaving location onto access
road. No BMPs apparent.



Rills on access road. No
BMPs apparent.



Rills on west side of location, evidence of sediment transport.



Rills from west side of location (previous picture) continuing into adjacent drainage.



Rills leaving location.



Former tank battery berm holding stormwater. Rill leaving location.



Rill leaving location.

11/18/2013

Inspection 673400105



Rill leaving location.

11/18/2013

Inspection 673400105



Rill leaving location.

11/18/2013

Inspection 673400105

