



Photo 1. View of eastern portion of project area from southeastern corner facing northward.



Photo 2. View from southeastern corner of project area toward center.



Photo 3. View of southern portion of project area from southeastern corner facing westward.



Photo 4. View of area of vegetation that appears burned in western portion of project area. This area should be re-seeded and weeds carefully monitored.