



Photo 1. View of kochia (*Kochia scoparia*) and Russian thistle (*Salsola tragus*) debris accumulated along the eastern portion of the project area.



Photo 2. View of revegetation in western portion of project area from southwestern corner facing northward.



Photo 3. View of revegetation in the southern portion of the project area from southwestern corner facing eastward.



Photo 4. View of culvert outlet along access road where it appears cobble BMP may not be sufficient to de-energize concentrated flows that are diverted from the well pad.