



Photo 1. View of Russian thistle (*Salsola tragus*) and kochia (*Kochia scoparia*) debris within southeastern portion of project area.



Photo 2. View of kochia and Russian thistle debris in eastern portion of project area.





Photo 3. View of large blocks of cement waste in northern portion of project area.



Photo 4. View of western portion of project area from southwestern corner facing northward.





Photo 5. View of large area in northern portion of project area that does not appear necessary for production operations. From northeastern corner facing center.



Photo 6. View of stormwater erosion along access road. A flow pattern can be seen on road and downstream (on left) where stormwater flows beneath wattles across road and down the road shoulder.