



Photo 1. View from northeastern corner of well pad facing center.



Photo 2. View of culvert outlet near entrance to well pad. Culvert is largely full of sediment.



Photo 3. View of rill erosion on shoulder of access road.



Photo 4. View of bar ditch on western side of access road. Stormwater flows along bar ditch are not sufficiently de-energized and causing erosional downcutting.



Photo 5. View of stormwater diversion along eastern edge of project area facing northward. A deteriorated silt trap berm and deteriorated straw wattles can be observed.



Photo 6. View of silt trap in southern portion of project area. A breach in the berm can be seen in the center of the photo.



Photo 7. View of stormwater erosion downstream from breach in silt trap shown in Photo 6, facing southward.