



Photo 1. View of well pad from northwestern corner facing center.



Photo 2. View of residual musk thistle from previous season within the interim reclamation area.





Photo 3. View of cut-slope in southwestern portion of well pad. Poor revegetation along cut-slope. Vegetation at the toe of the slope is largely cheatgrass (*Bromus tectorum*).



Photo 4. View of ruts approximately 12 inches deep within access road.





Photo 5. View of western edge of well pad where it appears stormwater flows over the edge, eroding the well pad surface.