



Photo 1. Birdseye view of musk thistle (*Carduus nutans*) seedlings within the interim reclamation area.



Photo 2. View of erosional channel along the southern edge of the access road.



Photo 3. View of erosional channel along the northern edge of the access road.



Photo 4. View of exposed pipe within the erosional channel on the southern edge of the access road.



Photo 5. View of sediment deposition (bottom) and stormwater erosion (top) occurring on the well pad cut slope.



Photo 6. View of erosional channels forming along the southwestern edge of the well pad.



Photo 7. View of erosional channels forming along the eastern edge of the well pad. Rig cable and debris can also be seen adjacent to guy line anchor.