

Federal 4-35

Inspection# 673401996

No capacity on tank label.
Overgrown berm.



Rills transporting sediment
down access road.



Rills transporting sediment down access road.



Sediment entering drainage.



Sediment entering drainage.



Rill leaving location.

11/18/2013


Inspection 673400105



Rill leaving location.

11/18/2013

Inspection 673400105



Rill leaving location.

11/18/2013

Inspection 673400105



Cuttings with no berm.

2/11/2015

Inspection 673401785



Cuttings with no berm.

3/10/2015

Inspection 673401899



Cuttings with no berm.

2/11/2015

Inspection 673401785



Waddles blocking culvert
at entrance.

3/10/2015

Inspection 673401899



Waddles blocking culvert at entrance.

3/10/2015

Inspection 673401899



Waddles falling into culvert at entrance.

2/11/2015

Inspection 673401785



Waddles falling into culvert
at entrance.

2/11/2015

Inspection 673401785



Vehicle tracking off of
location.

3/10/2015

Inspection 673401899



