



photo 1: Well sign, Apache Canyon 16-13



photo 2: Facing west towards the location.



photo 3: Facing southeast towards the access road. Erosion channels developed across the access road.



photo 4: Erosion channel along the access road.



photo 5: Facing south towards the location



photo 6: Guy line anchor is not properly marked.