

Image 1. Google earth (2015) image of project area in 2013. Ranch road crossing through northern portion of project area can be observed.




Image 2. Google earth (2015) image of project area in 1993. Ranch road crossing through northern portion of project area can be observed.



Photo 1. View of northern portion of well pad from northwestern corner facing eastward. An existing surface owner road crosses through this portion of the well pad.



Photo 2. View of surface owner road (two-track) where it continues westward from the well pad. Truck is on the road and is a contractor for surface owner who is improving this portion of the road for access to home site.



Photo 3. View of entrance to well pad area facing southeastward along road alignment.



Photo 4. View of southern portion of road shown in Photo 3. This is where it appears stormwater runoff is eroding downstream of the project area.



Photo 5. View of status of final reclamation from northeastern corner of well pad facing center.