



Photo 1. View of two-track road exiting western edge of working area facing northeastward. This road needs to be reclaimed.



Photo 2. View of two-track road exiting western edge of working area facing southwestward. This road needs to be reclaimed.



Photo 3. View of two-track road from southern portion facing northward.



Photo 4. View of new stormwater BMPs installed within the eastern portion of the project area facing northwestward toward the well pad.



Photo 5. View of new straw wattle installation on southern edge of working area.



Photo 6. View of new straw wattle installation within northwestern corner of project area.