



Photo 1. View of existing pit, pit liner, rig anchor, and sediment deposition on the well pad, facing northwestward.



Photo 2. View of erosion along cut-slopes on western edge of project area.



Photo 3. View of erosion of stockpiled soil in northwestern corner of project area.



Photo 4. View of stormwater erosion in diverted channel along northern edge of project area.



Photo 5. View of gravel on surface of access road.



Photo 6. View of musk thistle (*Carduus nutans*) plants from the previous season. These plants have produced seed that will become a new infestation during the 2015 growing season.



Photo 7. View of culvert inlet near the entrance to the well pad. It appears that a boulder has blocked the culvert and diverted the stream along the access road for approximately 700 feet.



Photo 8. View of erosional channel approximately 3 to 6 feet wide and 2 to 5 feet deep along access road.