

Coal Gulch 15-9

Inspection# 675201478

Concrete washout area with
no BMPs.



Disturbed area sloping away
from equipment with no
stormwater BMPs.



Debris on fill side of location
in disturbed area.



Debris near entrance of
location.



Debris on south east corner
of location.



Vegetation growing in tank
containment and on berms.



Storm water discharge
point. No BMPs in place.



Location: concrete wash out
visible, no stormwater BMPs
in place at time of
inspection.

