



Photo 1. View of eastern portion of project area from northeastern corner facing southward.





Photo 2. View of junk in northeastern corner of project area.





Photo 3. View of northern edge of working area from northeastern corner facing westward.





Photo 4. View of scattered junk and debris within project area from northwestern corner facing center.





Photo 5. View of what appears to be an oily rag on working surface of well pad.