



Photo 1. View of unused equipment in northern portion of working area.



Photo 2. View of good revegetation establishment within northern portion of the interim reclamation area.





Photo 3. View of erosional channel tunneling beneath the northern portion of the interim reclamation area.





Photo 4. View of erosional channel in northeastern portion of project area, flowing toward a wetland complex.





Photo 5. View of erosional channel shown in Photo 4. Stormwater has eroded this channel approximately 2.5 feet wide and 3.5 feet deep.





Photo 6. View of an erosional channel in the southeastern corner of the project area flowing toward the eastern wetland complex. This channel is approximately 2 to 3 feet wide and 4 feet deep.





Photo 7. View of several young Canada thistle plants within the interim reclamation area.