



Photo 1. View of rill erosion coming off of access road that needs to be monitored.



Photo 2. View of erosion that needs to be monitored in northeastern portion of project area.



Photo 3. View of northern portion of project area from northwestern corner of project area facing eastward.



Photo 4. View of western portion of project area from northwestern corner facing southward.



Photo 5. View of southern portion of project area from southwestern corner facing eastward.



Photo 6. View of cobble armoring BMP on southern portion of project area.