



Photo 1. View of kochia debris in southern portion of project area. Kochia appears to be inhibiting revegetation in this area.



Photo 2. View of hoary cress (*Cardaria draba*) in southern portion of project area.



Photo 3. Close up of hoary cress weeds that are close to flowering within southern portion of project area.



Photo 4. View of rills from stormwater flows in southeastern portion of project area. Little to no desirable vegetation is present on fill slope to filter stormwater flows.



Photo 5. View of northern portion of project area from northeastern corner facing westward..