



Photo 1. View of eastern portion of project area from southeastern corner facing northward.



Photo 2. View of northern portion of project area from northwestern corner facing eastward.





Photo 3. View of rill erosion along western edge of fenceline that needs to be monitored.



Photo 4. View of rill erosion in southwestern portion of project area that needs to be monitored.