



Photo 1. View of unused equipment and vegetation within the southwestern portion of the project area.



Photo 2. View of unused equipment within the southeastern portion of the project area.



Photo 3. View of more unused equipment within the southeastern portion of the project area.



Photo 4. View of straw wattles that appear to have been grazed (see adjacent hoof prints).



Photo 5. View of stormwater BMP and vegetation along southern slope of project area. These appear to be helping stabilize the location.



Photo 6. View of stormwater diversion drainage with straw blanket along northern edge of project area facing westward.