



photo 1: Well sign at the beginning of the access road



photo 2: Access road to the location has been widened to approximately 50 ft.



photo 3: Access road west to the location has been routed around the original access road.



photo 4: Erosion along the old access road has caused vehicle traffic to widen the road to approx. 50 ft.



photo 5: Center of the location facing south towards the production equipment.



photo 6: Tank battery at the location.



photo 7: Unused pipe near the pumpjack.



photo 8: Facing north at the location.