



Photo 1. View of erosional feature that has been re-graded in northern portion of project area.



Photo 2. View of cobble on well pad surface where it appears that concentrated stormwater flows exit the project area.



Photo 3. View of cobble lining along drainage adjacent to access road.



Photo 4. View of hydromulch on southern stormwater diversion channel and berm.