



Photo 1. View of musk thistle (*Carduus nutans*) within the project area.



Photo 2. View of Canada thistle (*Cirsium arvense*) along the western ditch bank.



Photo 3. View of erosion where it appears ditch bank has breached along western edge of project area.



Photo 4. View of standing water in driving surface of well pad.