

## Arroyo Project

Inspection# 6752010562

Location from SE corner. Top  
soil in process.



Location from SW corner.  
Top soil in process.





Location from NW corner.  
Top soil in process.



Location from NE corner.  
Top soil in process.





Drainage area on north side  
of location with depression  
for sediment retention.

