



photo 1: Facing south along the access road towards the location.



photo 2: Facing south along the access road. Erosion channel along the access road.



photo 3: Facing south towards the location.



photo 4: Pipe riser remains on the location (Lat/Long: 38.38077, -102.69541).



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 11: Northwest of the location facing southeast towards the location. Wood post remains.



photo 12: North of the location facing south towards the location.