



photo 1: Well sign, Valdez 44-6V



photo 2: Facing south along the access towards the location. Dead tree fell into roadway.



photo 3: Facing north towards the access road. Erosion channels are developing down the roadway.



photo 4: Erosion channel developing near the pipe risers at the south side of the location.



photo 5: West side of the location facing east.



photo 6: East side of the location facing west.