



Photo 1. View of Scotch thistle (*Onopordum acanthium*) rosette within the interim reclamation area.



Photo 2. View of western portion of project area from northwestern corner facing southward.



Photo 3. View from southwestern corner of well pad facing center. Revegetation of areas no longer in use appears to be progressing.



Photo 4. View of eastern portion of project area from northeastern edge of working area facing southward.