

SG 31-32 Pad

Inspection# 675201573

Erosion at entrance at
previous inspection.
(39.39341/-108.12961)



Erosion at entrance at follow
up inspection. (39.39341/-
108.12961)



Sediment migration into
vegetation at previous
inspection.



Sediment migration into
vegetation at follow up
inspection



Erosion on side of access
road.



Erosion on side of access
road.

