



photo 1: Well sign, Lorencito 1-20-34-66



photo 2: Southeast corner of the location facing northwest.



photo 3: Southeast corner of the location facing northwest.



photo 4: Facing north along the east side of the location. Erosion channels have developed off the pad.



photo 5: Erosion rills have formed transporting sediment off the pad at the east side of the location.



photo 6: The base of the pad where erosion is occurring.



photo 7: Approximately 200ft. east of the location silt fence debris remains.



photo 8: Approximately 200ft. east of the location, silt fence debris remains.