



photo 1: Access road west towards the location.



photo 2: Erosion rills/channels have formed transporting sediment and eroding the access road.



photo 3: No BMP's have been installed along the access road to prevent erosion from worsening.



photo 4: Facing east. Erosion channels running down the access road.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: Center of the location facing northwest towards the unstable cut of the pad.



photo 10: North side of the location. Unstable cut with material falling onto the pad.



photo 11: The pits remain open on the location.



photo 12: South side of the pad area has a steep rock base.