



Photo 1. View of western portion of project area from northwestern corner facing southward. Vegetation within interim reclamation area is largely Russian thistle (*Salsola tragus*) seedlings.



Photo 2. View from northwestern corner of project area facing center.





Photo 3. View of southern portion of project area from southwestern corner facing westward.



Photo 4. View of flowline running from southwestern corner of project area facing southwestward.