



Photo 1. View of project area from northwestern corner facing center. Good revegetation within the interim reclamation area.



Photo 2. View of southern portion of project area from southwestern corner facing southeastward. Stormwater diversion channel and berm have recently been maintained.



Photo 3. View of newly installed/maintained stormwater BMP along western edge of project area.



Photo 4. View of stormwater BMP within northern portion of interim reclamation area appears to be in good condition and functioning properly.



Photo 5. View of rig anchor that needs to be marked or removed.



Photo 6. Yellow toadflax (*Linaria vulgaris*) within the project area.