



Photo 1. View of southern edge of project area from southeastern corner facing westward.



Photo 2. View of southwestern portion of project area facing eastward.



Photo 3. View of unmarked rig anchor.



Photo 4. View of northern edge of project area from northwestern corner facing eastward.



Photo 5. View of musk thistle within project area.



Photo 6. View of sediment filled drainage and culvert on access road.



Photo 7. View of tire tracks driving off of road into vegetation along access road.



Photo 8. View of stormwater erosion channels that flow along both sides of access road.