



Photo 1. View of musk thistle (*Carduus nutans*) rosettes within the interim reclamation area.



Photo 2. View of erosional channel forming within eastern portion of the interim reclamation area.



Photo 3. View of another erosional channel forming within the eastern portion of the interim reclamation area.



Photo 4. View of western portion of project area from southwestern edge facing northward.