



Photo 1. View of musk thistle (*Carduus nutans*) rosette within the project area.





Photo 2. View of rill erosion from northern edge of the working area of the well pad.





Photo 3. View of rill erosion continued along the northern edge of the working area of the well pad.



Photo 4. View of rill erosion continued along the northern edge of the working area of the well pad.





Photo 5. View of good revegetation within northern portion of the interim reclamation area.



Photo 6. View of southern portion of the project area with good revegetation of areas no longer in use.