



Photo 1. View of musk thistle (*Carduus nutans*) plants within northeastern corner of well pad.



Photo 2. View of hundreds of Russian knapweed (*Acroptilon repens*; light green on left) within the northern portion of the interim reclamation area.



Photo 3. View of junk and debris on well pad.



Photo 4. Another view of junk on the well pad.



Photo 5. View of deep ruts and destroyed vegetation at well pad entrance.