



photo 1: South side of the location facing north.



photo 2: Southeast side of location facing west. Erosion channels have formed along the east side of the pad.



photo 3: South side of the location facing northwest towards the compressor.



photo 4: Center of the location facing north.



photo 5: West side of the location facing northwest towards the pump jack unit.



photo 6: West side of the location facing southeast.



photo 7: Facing towards the northwest side of the location at the office building.



photo 8: Storage unit at the northeast side of the location.