



photo 1: Well sign on the location, GE-76-94.



photo 2: Access road north towards the location.



photo 3: Facing back down the access road towards the south.



photo 4: Facing southeast towards the location.



photo 5: South side of the location facing south where flowline disturbance occurred.



photo 6: Possible soil stockpile on the east side of the location.



photo 7: West side of the location where a hydro-mulch was previously applied.



photo 8: Hydro mulch may have been applied to thick which may have impeded plant growth in this area.