



# FRAM OPERATING LLC

Hamilton 32-1  
NESE Sec 32, T13S, R95W  
Delta County, Colorado

## ELEVATION

R.B. 5,695  
G.L. 5,689  
KB 6'  
BHT  
Spud date: 12-2-2006  
API No. 05-029-06097-00

Lat: 38.87859  
Long: 108.02957

Not to scale

Prepared By: Harold Mayland  
Date: 11/10/2011

## Geological tops:

Mancos surface  
Dakota 2963

Conductor

11" hole  
SURFACE CSG: 8 5/8" 24# J55 ST&C @ 350'  
Cmt w/ 120 sks  
Cmt to surface

7 7/8" Hole  
Production Casing

I.D. 1.995  
Drift 1.901  
Burst 7,700  
Lin ft/bbl 0.004  
BBL/linft 258.650

I.D.  
Drift  
Burst  
Lin ft/bbl  
BBL/linft

	Qty	Length	Depth in hole
<b>Tubing</b>			
KB		6.00	6.00
Tbg Hanger		0.72	6.72
2 3/8" EU 8RD J55 4.6# tbg			6.72
<b>Estimated</b>			
<b>Total Joints</b>	<b>0</b>		
<b>Rods</b>			

## NOTE:

No casing. Looks like maybe 1 jt 5 1/2" stuck in well head  
Well head 8 5/8" x 5 1/2"  
5 1/2" x 2 3/8" probably 6' pup jt with 2 3/8" ball valve  
11-09-11 SITP approx 10-15 PSI  
Was told by Less Hamilton they filled hole with sand.

TD 3030'