



photo 1: New Elk 26-12



photo 2: Facing west towards the location from the access road.



photo 3: Gravel has recently been spread on pad surface and location has recently been reclaimed.



photo 4: Northeast corner of the location facing west. Culverts and rock outlet have been installed.



photo 5: North side of the location facing south.



photo 6: Northwest corner of the location facing east. Slope has recently been hydro mulched/seeded.



photo 7: West side of the location facing east.



photo 8: Slope along the south side of the location has been hydro mulched/seeded.



photo 9: Areas along the access road have recently been hydro mulched/seeded.



photo 10: The access road has recently been graded.