



photo 1: New Elk 30-03



photo 2: Facing west towards the location. Area between the road has no vegetation growth.



photo 3: Facing east towards the south side of the location which is not revegetated and is susceptible to erosion.



photo 4: Facing north towards the location.



photo 5: Northwest side of the location has minimal vegetation growth and shows signs of erosion.



photo 6: Northeast side of the location along the access road where erosion channel has developed.



photo 7: Erosion at the east side of the location is transporting sediment out into the pasture.



photo 8: East side of the location facing west towards the location.