


Surprise Unit 2-08H

Inspection# 673402219

Frack tree on wellhead, 2 frack tanks, 1 light tower, 1 sand catcher. Iron has been connected to wellhead and dirt moved to create ramp over pipes.



2 Sand catcher, 4 frack tanks (6 total on location), 4 portapotties.



4 frack tanks, 2 sand
catchers



Backhoe and workers
leaving location upon arrival
of inspector.



Man lift, hose rack, location
perimeter. No additional
downgradient perimeter
berming observed.



Only sign with on location. Ommix is no longer the operator.

Pit
40.925890, -108.327660

11/18/2014

Inspection 673400406

Cuttings with no berm.

2/11/2015

Inspection 673401785



Cuttings with no berm.

3/10/2015

Inspection 673401899



Cuttings with no berm.

2/11/2015

Inspection 673401785



Waddles blocking culvert
at entrance.

3/10/2015

Inspection 673401899



Waddles blocking culvert at entrance.

3/10/2015

Inspection 673401899



Waddles falling into culvert at entrance.

2/11/2015

Inspection 673401785



Waddles falling into culvert
at entrance.

2/11/2015

Inspection 673401785



Vehicle tracking off of
location.

3/10/2015

Inspection 673401899



