



Photo 1. View of newly installed diversion along western edge of working area.



Photo 2. View of cobble run-down in western portion of project area.



Photo 3. View of cobble run-down in northwestern portion of project area.



Photo 4. View of newly installed straw wattle near the top of the eastern cut-slope.



Photo 5. View of newly installed straw wattles within eastern diversion.