



Photo 1. View of tank battery from southern edge facing northward. Russian knapweed (*Acroptilon repens*) plants are visible in the foreground and rubber rabbitbrush (*Ericameria nauseosa*) and tumble mustard (*Sysimbrium altissimum*) in the background. Tank battery area does not appear to have been de-compacted and reclaimed.



Photo 2. View of rig anchor cable within well pad area.



Photo 3. View from northern edge of well pad facing southwestward. What appears to be cement debris is present in the mid-ground of photo. An area approximately 90 feet long and 15 feet wide that is largely devoid of vegetation is present on the well pad.



Photo 4. View of the beginning of Transect 1, within the project disturbance, facing northeastward.



Photo 5. Birdseye view of the midpoint along Transect 1, within the project disturbance. Vegetation left of foot is field bindweed (*Convolvulus arvensis*).



Photo 6. View of the beginning of Transect 2, reference transect that is outside of project disturbance, facing southwestward. Vegetation is comprised of native and non-native species such as crested wheatgrass (*Agropyron cristatum*), cheatgrass (*Bromus tectorum*), rubber rabbitbrush (*Ericameria nauseosa*) and tumble mustard (*Sysimbrium altissimum*).



Photo 7. Birdseye view of midpoint along Transect 2, reference transect that is outside of project disturbance. Vegetation here is comprised of tumbledustard, cheatgrass, field bindweed, and globemallow (*Sphaeralcea coccinea*).