



photo 1: Will sign



photo 2: Access road traveling north to the location may be inaccessible to emergency vehicles.



photo 3: Access road traveling north to the location may be inaccessible to emergency vehicles.



photo 4: Facing west towards the location at the cattle guard.



photo 5: Erosion is occurring along the access road traveling west towards the location.



photo 6: Sediment is being transported off of the access road out into the surrounding cultivated field.



photo 7: Facing west towards the equipment on location.



photo 8: Equipment at the location.



photo 9: Traveling south from the well site. Noxious weeds are growing along the roadside.



photo 10: Musk thistle (List B noxious weed) growing along the roadside.



photo 11: Facing north along the access road.



photo 12: Surrounding vegetation along the access road did not appear to have very many noxious weeds.