



Photo 1. View of western portion of project area from northern edge facing southward. Ruderal vegetation such as Musk thistle (*Carduus nutans*), yellow sweetclover (*Melilotus officinalis*), annual sunflower (*Helianthus annuus*), foxtail barley (*Hordeum brachyantherum*), and cheatgrass (*Bromus tectorum*) are growing within this area.





Photo 2. View of reclaimed pit area from western edge facing southeastward. This area does not appear to have been mulched and seeded as proposed in reclamation plan.





Photo 3. View of erosional channel within western portion of project area. This channel is approximately 8 inches deep and 6 inches wide.





Photo 4. View of sediment deposition along western edge of project area showing where sediment appears to be discharging outside of the project area straw wattles.





Photo 5. View of eastern project area from east facing northwestward. This area does not appear to have been mulched and re-seeded as proposed in the reclamation plan.





Photo 6. View of vegetation community adjacent to the project area from northeastern edge facing eastward. Vegetation here dominated by black sage (*Artemisia nova*), great basin sagebrush (*Artemisia tridentata*), and needle and thread grass (*Hesperostipa comata*).