

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400872884

Date Received:

07/23/2015

Spill report taken by:

CANFIELD, CHRIS

Spill/Release Point ID:

442507

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: DCP MIDSTREAM LP	Operator No: 4680	Phone Numbers
Address: 370 17TH STREET - SUITE 2500		Phone: (970) 590-6444
City: DENVER	State: CO	Zip: 80202
Contact Person: Sam Wood		Mobile: ()
		Email: swood@dcpmidstream.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400867268

Initial Report Date: 07/13/2015 Date of Discovery: 07/13/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSW SEC 29 TWP 2N RNG 68W MERIDIAN 6

Latitude: 40.113042 Longitude: -105.019497

Municipality (if within municipal boundaries): County: WELD

Reference Location:

Facility Type: PIPELINE

☐ Facility/Location ID No

☒ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): >=1 and <5

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify):

Weather Condition: Sunny/Overcast

Surface Owner: OTHER (SPECIFY)

Other(Specify): Private

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

An unmarked DCP Midstream line was struck by a KP-Kauffman excavator while doing work on one of their tank batteries near the intersection of CR 16.5 & CR 5. Condensate sprayed after the strike until the line was shut in as soon as possible. Remediation activities are set to begin immediately. More information will be supplied on the 10-day follow up report.

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
7/14/2015	Weld County LEPC	Gracie Marquez	-	

#1	Supplemental Report Date:	07/23/2015
FLUIDS	BBL's SPILLED	BBL's RECOVERED Unknown
OIL	0	0 <input type="checkbox"/>
CONDENSATE	2	1 <input type="checkbox"/>
PRODUCED WATER	0	0 <input type="checkbox"/>
DRILLING FLUID	0	0 <input type="checkbox"/>
FLOW BACK FLUID	0	0 <input type="checkbox"/>
OTHER E&P WASTE	0	0 <input type="checkbox"/>
specify: _____		
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>		
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>		
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit		
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature		
Surface Area Impacted:	Length of Impact (feet): <u>60</u>	Width of Impact (feet): <u>30</u>
	Depth of Impact (feet BGS): <u>5</u>	Depth of Impact (inches BGS): <u>60</u>
How was extent determined?		
<p>Tasman was dispatched to the Nelson Milton tank battery to install oil absorbent boom downgradient of a surface release that occurred from a line strike of a buried DCP valve by KPK. Excavation activities were initiated on Wednesday July 15th, and 8 truckloads of impacted material were removed from the site which included approximately 1-foot of material from the stained surface area as well as impacted soils that were observed near the broken valve and a buried KPK flowline. A Photo-ionization detector was used onsite to help guide delineation activities. Five soil samples were collected (SS01 – SS05) as illustrated in the attached field sketch and all samples were below COGCC standards.</p>		
Soil/Geology Description:		
Aquolls and Aquepts, flooded		
<div style="display: flex; justify-content: space-between;"> <div> Depth to Groundwater (feet BGS) <u>0</u> </div> <div> Number Water Wells within 1/2 mile radius: <u>8</u> </div> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div> If less than 1 mile, distance in feet to nearest <div style="display: flex; justify-content: space-between; margin-top: 5px;"> <div> Water Well <u>608</u> None <input type="checkbox"/> </div> <div> Surface Water <u>1130</u> None <input type="checkbox"/> </div> </div> <div style="display: flex; justify-content: space-between; margin-top: 5px;"> <div> Wetlands _____ None <input checked="" type="checkbox"/> </div> <div> Springs _____ None <input checked="" type="checkbox"/> </div> </div> <div style="display: flex; justify-content: space-between; margin-top: 5px;"> <div> Livestock <u>800</u> None <input type="checkbox"/> </div> <div> Occupied Building <u>630</u> None <input type="checkbox"/> </div> </div> </div> </div>		
Additional Spill Details Not Provided Above:		

CORRECTIVE ACTIONS

#1	Supplemental Report Date: 07/23/2015
Cause of Spill (Check all that apply) <input checked="" type="checkbox"/> Human Error <input type="checkbox"/> Equipment Failure <input type="checkbox"/> Historical-Unknown	
<input type="checkbox"/> Other (specify) _____	
Describe Incident & Root Cause (include specific equipment and point of failure)	
A DCP Midstream line was not located and was stuck by a KPK excavator doing work on the Milton Nelson tank battery.	
Describe measures taken to prevent the problem(s) from reoccurring:	
The area has been re-mapped to ensure all pipes are more accurately located in the future.	
Volume of Soil Excavated (cubic yards): 80	
Disposition of Excavated Soil (attach documentation) <input checked="" type="checkbox"/> Offsite Disposal <input type="checkbox"/> Onsite Treatment	
<input type="checkbox"/> Other (specify) _____	
Volume of Impacted Ground Water Removed (bbls): 0	
Volume of Impacted Surface Water Removed (bbls): 0	

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Remediation and excavation activities are still in progress. Another supplemental eForm-19 will be submitted upon conclusion of these activities along with an NFA request. Please contact me with any questions or concerns.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Sam Wood

Title: Compliance Coordinator Date: 07/23/2015 Email: swood@dcpmidstream.com

Attachment Check List

Att Doc Num	Name
400873164	SITE MAP
400873166	ANALYTICAL RESULTS
400873167	ANALYTICAL RESULTS

Total Attach: 3 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)