

# ENCANA OIL & GAS (USA) INC

K10 pad

Location # 335676

# EnCana K10 location # 335676



# Unstable cut slope



Water diversion ditch above cut slope has collapsed allowing rock and sediment migrate.

