

Moffat County 1-8

Inspection# 673402235

Erosion occurring off of access road at entrance. Seacan and materials in background.



Close up of access road erosion. Hard hat for scale.



Erosion on access road and location overview illustration no interim reclamation has been performed.

