

Voloshin 3-25

Inspection# 673402254

Sloughing onto location. No
BMPs apparent.

Inspection 673402254
7/17/2015



Rill leaving west side of
location. Sloughing
material visible in
background.

Inspection 673402254
7/17/2015



Rill leaving location on west side. Hard hat for scale.

Inspection 673402254
7/17/2015



View looking down on rill and hard hat from previous photo. Location borders drainage on west side.

Inspection 673402254
7/17/2015



Sloughing in far background,
rill with hard hat in middle
and sediment migration in
foreground.

Inspection 673402254
7/17/2015



Sediment migration
approximately 30 feet from
location perimeter. Silt
fence is damaged and no
longer in place. Sediment
migrating through fence. Silt
fence is only BMP apparent.

Inspection 673402254
7/17/2015



Rill leaving location during
runoff. No stormwater
BMPs apparent.

Inspection 673401910
3/16/2015

