



Unlabeled production tanks on location.



Excessive weed growth on location (View to SW)



Weeds (Thistles/ Noxious) on well pad (SE Corner location)



Weeds/ excessive vegetation on access road near well pad entrance.



Stormwater damage/ erosion on well site access road.



Stormwater damage on well site access road; Stormwater channel in access road.



Access road view to south.



Wash crossing/ low lying area with deep vehicle rutting; Difficult crossing in wet weather.



Open thief hatch on production tank.